

Supporting Documents

REDACTED

Not within OHSI's Terms of Reference.
Within exclusive jurisdiction of TSB.

Sikorsky Alert Service Bulletin 92-63-014 (Original)

The two (2) pages that follow comprise the first two pages of the original Sikorsky Alert Service Bulletin ASB 92-63-014, which relates to replacement of the main gearbox oil filter housing mounting studs within 1250 flight hours or one year.