

Supporting Documents

REDACTED

Not within OHSI's Terms of Reference.
Within exclusive jurisdiction of TSB.

Sikorsky Alert Service Bulletin 92-63-014A (Revised)

The twelve (12) pages that follow comprise the revised Sikorsky Alert Service Bulletin ASB 92-63-014A, which relates to replacement of the main gearbox oil filter housing mounting studs prior to next flight.