

REDACTED

Not within OHSI's Terms of Reference.
Within exclusive jurisdiction of TSB.

Emergency Procedures Check Lists - Gearbox Malfunctions

The pages that follow comprise the following:

- Section of the Sikorsky S-92A Rotorcraft Flight Manual (RFM) Approved 21 March 2005, revised 9 April 2008 that pertains to a main gearbox malfunction. (total of four pages with revision dates of 17 July 2007 on two pages and 9 April 2009 on the other two pages).

- Section of Cougar S-92A Standard Operating Procedures (SOPs) that pertains to a main gearbox malfunction (two pages dated 15 April 2008).

- Cougar S-92A Cockpit Emergency Checklist revised post-accident on 28 March 2009.

Note: The Cougar S-92A Standard Operating Procedures (SOPs) revised post-accident on 28 March 2009 are contained within the Cougar's Preliminary Return to Service Plan already included in this section.